

PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Carlsbad State: Ca
 ZIP: 92008 Country: U.S.A.
 Latitude: N33 58.5 Longitude: W117 38.2
(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 07/04/2015 Local Time: 3:15pm
mm/dd/yyyy Time Zone: Pacific

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N8075P
 Manufacturer: Piper
 Model: Pa 18-150
 Serial Number: 8050
 Year of Manufacture: 1964
 Amateur-Built: ☐ Yes ☒ No If Yes: ☐ Kit/Plans ☐ Original Design Make: _____

- ☐ IFR-Equipped and Certified
☐ Commercial Space Flight
☐ Unmanned Aircraft

Maximum Gross Weight: 1750 lbs
 Weight at Time of Accident/Incident: 1450 lbs
 Number of Seats: 2 Flight Crew Seats: _____
 Cabin Crew Seats: _____ Passenger Seats: _____
 Number of Engines: 1

Category of Aircraft

- ☒ Airplane
☐ Balloon
☐ Blimp/Dirigible
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift
☐ Rocket
☐ Ultralight
☐ Unknown

Type of Airworthiness Certificate (Check all that apply)

- Standard**
☒ Normal
☐ Aerobatic
☐ Balloon
☐ Commuter
☐ Transport
☐ Utility
☐ Certificate of Authorization or Waiver (COA)
☐ None
- Special**
☐ Restricted
☐ Limited
☐ Provisional
☐ Special Flight
☐ Experimental
☐ Special Light-Sport
☐ Experimental Light-Sport
☐ Unknown

Landing Gear (Check all that apply)

- ☐ Retractable
☐ Tricycle ☒ Tailwheel
☐ Amphibian ☐ High Skid
☐ Emergency Float ☐ Skid
☐ Float ☐ Ski
☐ Hull ☐ Ski/Wheel
☐ Other Launch/Recovery System
☐ None ☐ Unknown

Engine Type (Select one)

- ☒ Reciprocating ☐ Liquid Rocket
☐ Turbo Shaft ☐ Solid Rocket
☐ Turbo Prop ☐ Hybrid Rocket
☐ Turbo Jet ☐ None
☐ Turbo Fan ☐ Unknown
☐ Electric

Fuel System Type (Reciprocating)

- ☒ Carburetor ☐ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Serial	Manufacturer's Serial Number	Date of Mfg. <i>mm/dd/yyyy</i>	Rated Power ☐ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	<u>Lycoming</u>	<u>O320 B2B</u>	<u>L-494-39</u>	<u>1964</u>	<u>160</u>	<u>5949</u>		<u>1004</u>
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour ☐ Continuous Airworthiness
☐ AAIP ☐ Conditional Inspection
☒ Annual ☐ Unknown

Date Last Inspection: 10/03/2014
mm/dd/yyyy

Airframe Total Time: 7146 hrs
 hours measured at (Select one)
☐ Last Inspection ☒ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☒ Annual
☐ Conditional (Amateur-built only)
☐ Manufacturer's Inspection Program
☐ Other Approved Inspection Program (AAIP)
☐ Continuous Airworthiness
☐ Other, specify: _____

Description of Fire Extinguishing System

- ☒ None
☐ Specify: _____

Propeller 1

- ☒ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: McCauley
 Model: 1A 175 GM8242

Propeller 2

- ☐ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: _____
 Model: _____

ELT Installed: ☒ Yes ☐ No

If Yes:
 ELT Manufacturer: Leigh
 Model or Part No.: Sharc 7
 TSO No.: ☒ C91 (121.5 MHz) ☐ OC91a (121.5 MHz)
☐ OC126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No
 Was ELT still connected to antenna? ☒ Yes ☐ No
 Did ELT Activate? ☒ Yes ☐ No

If activated:
 Did ELT Aid in Locating Aircraft: ☐ Yes ☒ No

If not activated:
 Indicate Reason: ☐ Impact Damage
☐ Fire Damage
☐ Battery Expired/Damaged
☐ Unknown

Additional Equipment (Check all that apply)

- ☐ ADS-B
☐ Airframe Parachute
☐ Angle of Attack Indicator
☐ Autopilot
☐ Data Recorder
☐ Electronic Flight Bag or Handheld Device
☐ Electronic Multifunction Display
☐ Electronic Primary Flight Display
☐ Handheld GPS
☐ Heads Up Display
☐ Onboard Weather
☐ Satellite Tracking Device
☐ Stall Warning System
☐ Video Recording Device
☐ Other, Specify: _____

Registered Aircraft OwnerName: AIR ADS INCCity: EL CAJONState: CA ZIP: 92020Fractional Ownership Aircraft: ☐ Yes ☒ NoCountry: U.S.A.**Operator of Aircraft** ☒ Same As Registered Owner☒ Same Address as Registered Owner

Name: _____

City: _____

Doing Business As: _____

State: _____ ZIP: _____

Air Carrier/Operator Designator (4 Character Code): _____

Country: _____

Operating Certificates Held

(Check all that apply)

- ☒ None
- ☐ Flag Carrier Operating Certificate (FAR 121)
- ☐ Supplemental
- ☐ Air Cargo
- ☐ Foreign Air Carriers (FAR 129)
- ☐ Rotorcraft External Load (FAR 133)
- ☐ Commuter Air Carrier (FAR 135)
- ☐ On-Demand Air Taxi (FAR 135)
- ☐ Commercial Air Tour (FAR 136)
- ☐ Agricultural Aircraft (FAR 137)
- ☐ Pilot School (FAR 141)
- ☐ Certificate of Authorization or Waiver (COA)
- ☐ Commercial Space Transportation Experimental Permit
- ☐ Commercial Space Transportation License
- ☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
- ☐ FAR 103 ☐ FAR 133 ☐ FAR 431
- ☐ FAR 121 ☐ FAR 135 ☐ FAR 435
- ☐ FAR 125 ☐ FAR 137 ☐ FAR 437

- ☐ FAR 91 Special Flight
- ☐ Non-US, Commercial
- ☐ Non-US, Non-commercial

☐ Public Aircraft (Select one)

- ☐ Armed Forces
- ☐ Federal
- ☐ State
- ☐ Local

☐ Unknown**Revenue Operation for FAR 121, 125, 129, 135**

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
- ☐ Non-Scheduled or Air Taxi ☐ International

- ☐ Passenger
- ☐ Cargo
- ☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
- ☐ Aerial Observation ☐ Flight Test
- ☐ Air Drop ☐ Glider Tow
- ☐ Air Race/Show ☐ Instructional
- ☒ Banner Tow ☐ Other Work Use
- ☐ Business ☐ Personal
- ☐ Executive/Corporate ☐ Positioning
- ☐ External Load ☐ Skydiving
- ☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION** (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)

Airport Name: _____

Distance From Airport Center: _____ sm

Airport Identifier: _____

Direction From Airport: _____ degrees true

Proximity to Airport: ☐ Off Airport/Airstrip ☐ On Airport/Airstrip ☐ N/A

Airport Elevation: _____ ft msl

Runway Information

Runway ID: _____ (L/R/C) Length: _____ ft Width: _____ ft

Runway/Landing Surface (Check all that apply)

- ☐ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
- ☐ Concrete ☐ Gravel ☐ Metal/Wood
- ☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☐ Dry ☐ Snow-Compacted ☐ Water-Calm
- ☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
- ☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
- ☐ Rough ☐ Snow-Wet ☐ Wet
- ☐ Rubber Deposits ☐ Soft
- ☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
- ☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☐ Go Around
- ☐ Initial Climb ☐ Final ☐ Aborted Landing (after touchdown)
- ☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)

- ☐ None
- ☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
- ☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
- ☐ VOR/TVOR ☐ ILS ☐ ASR
- ☐ VOR/DME ☐ Localizer Only ☐ Visual
- ☐ TACAN ☐ LOC-back course ☐ Contact
- ☐ RNAV ☐ Circling
- ☐ Unknown

VFR Approach (Check all that apply)

- ☐ None
- ☐ Traffic Pattern ☐ Stop and Go
- ☐ Straight-In ☐ Touch and Go
- ☐ Valley/Terrain Following ☐ Simulated Forced Landing
- ☐ Go Around ☐ Forced Landing
- ☐ Full Stop ☐ Precautionary Landing
- ☐ Unknown

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☒ Substantial
☐ Minor ☐ Destroyed
 ☐ Unknown

Aircraft Fire

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

Upon landing the aircraft nosed over resulting the following: A bent propeller, spinner assembly bent engine cowl, broken engine mount and damaged fuselage attach mount. Also, right wing has a bent front spar and damaged ribs and bent rear lift strut. Aircraft received salt water and sand to wings and fuselage. Also, a broken windshield. Aircraft avionics and instruments have salt water damage.

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

On July 4th 2015 the aircraft was "topped off" with 100 low lead avgas resulting in 48 gallons being available for a 4 hour flight. The flight departed at 12:20 local time. At approximately 3:10 the aircraft landed on the beach at Carlsbad CA. and flipped over during the roll out. Investigating personnel noted the fuel selector was on the left tank. The selector was then placed in the off position. The aircraft was then placed on a flatbed truck and escorted by police and fire personnel to the nearby Palomar airport. On the 6th I presented the aircraft records to the FAA inspection team. I looked inside the aircraft cockpit area and viewed the left tank site gauge and observed no fuel visible. I then proceeded to the right tank and removed the fuel tank filler cap. Placing a finger inside the opening I felt fuel at the top of the tank. I then sampled some fuel from the sump at the rear of the tank. Avgas was present. I then proceeded to the left tank to sample from the rear sump no avgas was available. I then proceeded to the Gascolator located on the fire wall to see if any fuel was available no fuel was available. During the 3 hour flight and forced landing the fuel selector never moved from the left tank.

RECOMMENDATION (How could this accident/incident have been prevented?)

Operator/Owner Safety Recommendation

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)

Was there Mechanical Malfunction/Failure? ☐ Yes ☒ No
(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

Total Time/Cycles
On Part

____ Hours

____ Cycles

Time Since This Part
Inspected/Overhauled

____ Hours

FUEL & SERVICES INFORMATIONFuel on Board at Last Takeoff
(Convert from pounds, as necessary)

48

Gallons

Fuel Type

☐ 80/87☐ 115/145☐ Jet B☐ Other, specify _____☒ 100 Low Lead☐ Jet A☐ JP8☐ 100/130☐ Jet A-1☐ Automotive

Other Services, if Any, Prior to Departure

EVACUATION OF AIRCRAFTWas an emergency evacuation of the aircraft performed? ☐ Yes ☐ No

Method of Exit – Describe how the occupants exited and how many occupants evacuated each location

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)

Aircraft Registration Number

Manufacturer: _____

Model: _____

Damage to Other Aircraft

☐ Destroyed☐ Minor☐ Substantial☐ None

Registered Owner of Other Aircraft

Pilot of Other Aircraft

Name: _____

Name: _____

City: _____

City: _____

State: _____ ZIP: _____

State: _____ ZIP: _____

Country: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

07 30 2015
mm/dd/yyyy

Name of Pilot/Operator: AIR ADS INC.

Signature: [Redacted]

-- or --



Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: _____

Title: _____

Signature: _____

-- or --



Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.
WPR15CA207

Reviewed by NTSB Regional Office
Federal Way, WA

Name of Investigator
Howard Plagens

Date Report Received