



Photo 1 – Onsite View of Valley



Photo 2 – Onsite Wreckage



Photo 3 – Onsite Wreckage



Photo 4 – Onsite Wreckage



Photo 5 – Onsite Wreckage



Photo 6 – Onsite Wreckage Right Wing



Photo 7 – Follow-up Examination



Photo 8 – Follow-up Examination



Photo 9 – Follow-up Examination