



Photo 1 – Fire Damage



Photo 2 - Separated Tailpipe



Photo 3 - Battery




Photo 4 - Battery Cables