



Photo 1 – Main wreckage overview (photo provided by AvTech)



Photo 2 – Tail boom (photo provided by AvTech)



Photo 3 – Fuselage ruminants (photo provided by AvTech)



Photo 4 – Tail boom with tail rotor blade (photo provided by AvTech)



Photo 5 – Engine and main rotor mast (photo provided by AvTech)



Photo 6 – Main rotor hub and blades (photo provided by AvTech)



Photo 7 – Tail rotor drive shaft (photo provided by AvTech)



Photo 8 – Tail rotor (photo provided by AvTech)