



Photo 1 – Helicopter at Accident Site



Photo 2 – Dolly (Helicopter in Background)



Photo 3 – Dolly Front Edge Scratch



Photo 4 - Dolly Front Edge Scratch




Photo 5 – Dolly



Photo 6 – Helicopter Landing Attempt (Video Excerpt)



Photo 7 - Helicopter Landing Attempt (Video Excerpt)



Photo 8 - Helicopter Landing Attempt (Video Excerpt)



Photo 9 - Helicopter Landing Attempt (Video Excerpt)



Photo 10 - Helicopter Landing Attempt (Video Excerpt)



Photo 11 - Helicopter Spinning on the Ramp (Video Excerpt)