



Photo 1 – Engine and Forward Cabin at Accident Site



Photo 2 – Right Wing



Photo 3 – Left Wing and Center Section



Photo 4 – Pilots Jacket and Cannula



Photo 5 – Oxygen Bottle 1



Photo 6 – Oxygen Bottle 2




Photo 7 – Autopilot VOR/LOC Coupler Assembly



Photo 8 – Autopilot Panel Assembly