




Photo 1 – View to Northwest of Aircraft at Accident Site



Photo 2 – View to Southeast Through Railroad Car Wash Building of Left Wing



Photo 3 – View of Bottom of Horizontal Stabilizers and Elevator



Photo 4 – Remnants of Right Wing and Right Engine at Accident Site



Photo 5 – Left Wing Inboard and Outboard Fuel Tank Caps



Photo 6 – Left Engine Carburetor Fuel Bowl



Photo 7 – Left Engine Fuel Pump



Photo 8 – Surveillance Image of Accident Airplane (Courtesy of Bay Area Rapid Transit)



Photo 9 - Surveillance Image of Accident Airplane (Courtesy of Bay Area Rapid Transit)



Photo 10 - Surveillance Image of Accident Airplane (Courtesy of Bay Area Rapid Transit)