

RIGHT
\$ 4.95^{xx}



The Standard

PROPELLER LOG

ASA-SP-L

☐ HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS

Year: 2015	Total Time in Service	Description H03BS: 2913.3
Date: 3/2	3607.3	I CERTIFY THAT THIS PROP WAS INSPECTED IN ACCORDANCE WITH
Next Inspection Due:	Time Since Overhaul	AM 100 HOUR INSPECTION. APPROVED FOR RETURN TO SERVICE
	548.3	Mech. Cert. # or Repair Station # A&P [REDACTED] [REDACTED]

Year: 2016	Total Time in Service	Description H03BS: 3046.6
Date: 5/2	3740.6	I CERTIFY THAT THIS PROP WAS INSPECTED IN ACCORDANCE
Next Inspection Due:	Time Since Overhaul	WITH A 100 HOUR INSPECTION AND IS APPROVED FOR RETURN
	681.6	TO SERVICE Mech. Cert. # or Repair Station # A&P [REDACTED] [REDACTED]

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due:	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____