



Photo 1 – Glider as it came to rest



Photo 2 – Glider viewed from front



Photo 3 – Instrument panel following recovery



Photo 4 – Google Earth view of accident flight data




Photo 5 – Google Earth view of accident flight data with accident site location