



Photo 1 – Forward Quartering View of Airplane at Accident Site



Photo 2 – View of Accident Airplane from Left Wing



Photo 3 – View of Right Main Landing Gear Aft Tube Rod End




Photo 4 – Right Main Landing Gear Rod End