



Photo 1 – View of Helicopter at Accident Site (Courtesy of Federal Aviation Administration)



Photo 3 – View of Main Rotor Blade



Photo 4 – View of Trailing Edge Damage to Main Rotor Blade



Photo 5 – View of Helicopter Tailboom



Photo 6 – Aft View of Main Wreckage at Accident Site