



Photo 1 – Right side view of helicopter before accident.



Photo 2 – Close up of intact Simplex pump system.



Photo 3 – View of pump location to air intake.



Photo 4 – View of pump system after accident.