



**Photo 1 – View of accident site (courtesy of the operator)**




**Photo 2 – View of accident site (courtesy of the operator)**




**Photo 3 – View of transmission drag pin (courtesy of the operator)**



**Photo 4 – View of main driveshaft (courtesy of the operator)**



**Photo 5 – View of main driveshaft (courtesy of the Department of Interior)**



**Photo 6 – View of lower transmission housing (courtesy of the Department of Interior)**



**Photo 7 – View of main rotor mast (courtesy of the Department of Interior)**




Photo 8 – View of pylon mount (courtesy of the NTSB)