




Photo 1 – Flight Track Data and Accident Site Location



Photo 2 - Accident Site, Main Wreckage (Photo courtesy of the FAA)



Photo 3 – Main Wreckage, Rear Right View



Photo 4 – Main Wreckage, Left View



Photo 5 – Cabin Damage and Entry Point of Tree Limb



Photo 6 – Cabin Damage and Entry Point of Tree Limb



Photo 7 – Cabin Damage and Exit Point of Tree Limb