



Photo 1 – View of the main wreckage at the accident site.



Photo 2 – Recovered main wreckage.



Photo 3 – Recovered right engine.



Photo 4 – Recovered left engine.



Photo 5 – Fuel Selector Handles



Photo 6 - Fuel Selector Handles



Photo 7 – Left Engine Carburetor Float



Photo 8 – Recovered wreckage.