



**Photo 1 – View of Vertical Stabilizer and Rudder at Accident Site (Courtesy of Federal Aviation Administration)**



**Photo 2 – View of Outboard Left Wing (Courtesy of Federal Aviation Administration)**



**Photo 3 – Wood Debris Pile Impacted by Accident Airplane (Courtesy of Federal Aviation Administration)**



**Photo 4 – Active Runway at the Time of the Accident (Courtesy of Federal Aviation Administration)**