



*Figure 1 Front view of aircraft in field*



*Figure 2 Damage to fuselage and wings*



*Figure 3 Rear view of aircraft*



*Figure 4 Upper crank case damage*



*Figure 5 Cylinder 3 damage*



*Figure 6 Cylinder 3 valve stem and guide*



*Figure 7 Alternative view of cylinder 3 valve stem and guide*