

WPR17LA090
FAA On-Scene Photographs



Figure 1 - Airplane with Collapsed NLG at Final Stopping Point

WPR17LA090
FAA On-Scene Photographs



Figure 2 - Damaged Right Wing Outboard Section

WPR17LA090
FAA On-Scene Photographs



Figure 3 - Damaged Tailcone and Right Horizontal Stabilizer

WPR17LA090
FAA On-Scene Photographs



Figure 4 - Damaged Right Horizontal Stabilizer and Elevator