




Photo 1 – Accident site.



Photo 2 – Wreckage pulled from river.



Photo 3 – Wreckage inverted after gusty winds.



Photo 4 - Wreckage inverted after gusty winds.



Photo 5 - Wreckage inverted after gusty winds.



Photo 6 - Wreckage with the wings removed.



Photo 7 – Wreckage with the wings removed.