




As received pieces.

WPR17LA131




Portion of brace assembly with fracture


WPR17LA131



Portion of link assembly with fractured rod end



Fractured portion of swivel bearing assembly



Pieces of fractured trunnion

WPR17LA131



Bag with extraneous pieces