



**Photo 1 – Accident Site (Courtesy of Federal Aviation Administration)**



**Photo 2 – Aft View of Helicopter at Accident Site (Courtesy of Federal Aviation Administration)**



**Photo 3 – Tailboom with Dents and Protrusions (Courtesy of Federal Aviation Administration)**