



Photo 1 – Accident site.



Photo 2 – Accident site.



Photo 3 – Accident Site



Photo 4 – Right main landing gear position switch.




Photo 5 – Left main landing gear position switch.