

N7628L

Wednesday, July 26, 2017
11:23 AM



Came to rest

Wrinkled skin that
disappeared after
placing aircraft in
hanger



Right line

Thick mark on left
is keel.

Smaller on right
is right nose gear
door




Right wing
pou toon




Keel Damage



Right main
gear door lock
light switch
w/ No black cap?



left gear
same as above
but w/ black
cap?



but
cap?

