



Photo 1 – Wreckage examination.



Photo 2 – Auxiliary fuel pump switches (centered).



Photo 3 – Fuel captured.




Photo 4 – Fuel pressure switch.



Photo 5 – Left engine spark plugs.




Photo 6 – Left engine tachometer generator and oil screen cap.




Photo 7 – Right engine oil screen cap.




Photo 8 – Right engine belt driven alternator adjustment hardware safety wire.



Photo 9 – Inline fuel screen.