



Photo 1 – Aerial view of the accident site.



Photo 2 – Impacted power pole.



Photo 3 - Aerial view of the main wreckage



Photo 4 – Aerial view of the main wreckage.



Photo 5 – Impacted pole.



Photo 6 – Right outboard wing.



Photo 7 – Right propeller assembly.



Photo 8 – Right propeller assembly.



Photo 9 – Left propeller assembly and main wreckage.



Photo 10 – Left propeller assembly.



Photo 11 – Left propeller assembly.



Photo 12 – Left propeller assembly and airplane battery.



Photo 13 – Left engine nacelle and wing.



Photo 14 – Left side of empennage.



Photo 15 – Front right side of airplane.



Photo 16 – Left engine nacelle.



Photo 17 – Left wing damage.



Photo 18 – Right propeller blade separation.



Photo 19 – Right wing section.