



Photo 1 – Airplane at Accident Site



Photo 2 - Right Fuel Tank Drain Valve and Tank Breach



Photo 3 - Streaks Under Right Fuel Tank