

Factual Report – Attachment 2
Graphics

AIR TRAFFIC CONTROL

WPR18FA141

N2377R	4334	KBOI	KBOI 4MY
C182/T	P1802	10R/33 H	
272	VFR		

Figure 1 - Flight progress strip generated by the clearance delivery controller.




Figure 2 - Graphic showing the first radar target of the accident aircraft and travelling northbound.




Figure 3 - Graphic showing the last radar target of the accident aircraft before the accident sequence.




Figure 4 - Graphic showing the reported accident location and a possible track of the accident aircraft. The track was established after the loss of radar contact and cannot be confirmed as the accident aircraft.