



**Photo 1 – Overview of Accident site (Photo Courtesy of Fire Department)**



**Photo 2 – Tree (Photo Courtesy of Fire Department)**



**Photo 3 – View of the tree from the accident site (Photo Courtesy of Sheriff's Department)**



**Photo 4 – Main Wreckage (Photo Courtesy of Sheriff's Department)**



**Photo 5 – Undercarriage of Airplane (Photo Courtesy of Sheriff's Department)**



**Photo 6 – Portion of the Left Wing in Tree (Photo Courtesy of Sheriff's Department)**



**Photo 7 – Propeller Blade (Photo Courtesy of FAA)**



**Photo 8 – Other Propeller Blade (Photo Courtesy of FAA)**



**Photo 9 – Engine (Photo Courtesy of FAA)**



**Photo 10 – Engine (Photo Courtesy of FAA)**



**Photo 11 – Right Side of Main Wreckage (Photo Courtesy of FAA)**



Photo 12 – Hour Meter (Photo Courtesy of FAA)