



Photo 1 – View of Accident Airplane at Accident Site (Courtesy of Federal Aviation Administration)



Photo 2 – View of Accident Airplane Instrument Panel at Accident Site (Courtesy of Federal Aviation Administration)



Photo 3 – Engine Prior to Examination



Photo 4 – Camshaft Intake Camlobe for Cylinder Nos. 3 and 4