



Photo 1 – Airplane at Accident Site (Courtesy of Federal Aviation Administration)



Photo 2 – View of Accident Airplane from Right Wing (Courtesy of Federal Aviation Administration)



Photo 3 – Left Wing Root



Photo 4 – Forward View of Accident Airplane




Photo 5 –Engine Accessory Case with Separated Fuel Line (Courtesy of Federal Aviation Administration)