



Photo 1 – Onsite Photo



Photo 2 – Main wreckage, engine cowling



Photo 3 - Fuel selector handle



Photo 4 – Left side of the uncowed engine.



Photo 5 - Spark plug electrode area



Photo 6 – Gascolator pickup screen