



Photo 1 – accident site photo of forward area of airplane at rest



Photo 2 – accident site photo of left side of airplane at rest looking aft from just in front of engine



Photo 3 – accident site photo of airplane at rest as viewed from left rear