



Photo 1 – Forward Quartering View of Accident Airplane (Courtesy of Tohono O’Odham Nation Police Department)



Photo 2 – Top Engine Cowling (Courtesy of Tohono O’Odham Nation Police Department)



Photo 3 – View of Outboard Right Wing (Courtesy of Tohono O’Odham Nation Police Department)



Photo 4 – View Cylinder No. 4 and Fragmented Parts (Courtesy of Piper Aircraft Company)



Photo 5 – Cylinder Nos. 2 and 4 (Courtesy of Piper Aircraft Company)