



Photo 1 – Accident site, aft left view of the wreckage. (Courtesy of the FAA)



Photo 2 – Accident site, tailboom separation and main rotor blade damage. (Courtesy of the FAA)



Photo 3 – Accident site, front right view of the wreckage. (Courtesy of the FAA)



Photo 4 – Accident site, debris field. (Courtesy of the FAA)



Photo 5 – Accident site, tail rotor assembly and main wreckage.(Courtesy of the FAA)



Photo 6 – Accident site, left rear view of the wreckage.(Courtesy of the FAA)



Photo 7 – Accident site, right rear view of the wreckage. (Courtesy of the FAA)