

WPR18TA223
Photos courtesy KAPC



Figure 1 - Airplane on Levee



Figure 2 - Airplane on Levee

WPR18TA223
Photos courtesy KAPC



Figure 3 - Underside

WPR18TA223
Photos courtesy KAPC



Figure 4 - Airplane Underside

WPR18TA223
Photos courtesy KAPC



Figure 5 - Left Wing Damage

WPR18TA223
Photos courtesy KAPC



Figure 6 - Right Side View