



Photo 1 – N11QP Left View showing Left Sliding Door Opening



Photo 2 -Left Door Opening



Photo 3 – Left Side Sliding Door Upper Track



Photo 4 – Left Side Sliding Door Lower Track



Photo 5 – Plastic Sliding Door Latch



Photo 6 -Main Rotor Blades Showing Damage circled in Red