



**Photo 1 – View of the accident site. Courtesy of the La Verne Fire Department.**



**Photo 2 - View of the accident site. Courtesy of the La Verne Fire Department.**



**Photo 3 – View of the main wreckage.**



**Photo 4 – View of the wreckage debris path. Courtesy of the La Verne Fire Department.**



**Photo 5 - View of the propeller.**



**Photo 6 – View of portions of cowling and left wing tip.**



**Photo 7 – Recovered wreckage.**



**Photo 8 – Recovered engine.**