



Photo 1 – View of the accident site and main wreckage.



Photo 2 - View of the accident site and main wreckage.



Photo 3 – View of right wing.



Photo 4 – View of the forward portion of the airframe and engine.



Photo 5 – View of the main wreckage and left wing.




Photo 6 – View of the fuel selector valve handles.



Photo 7 – View of the engine.