

n or Repair

ND

YEAR: DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				2-1-2019 Hobbs 1962.5 TT 1962.5 Repacked main wheel bearings. Inspected ELT as per FAR 91.207. Batteries due on 2024. I certify that this Airframe has been inspected IAW a Condition Inspection and was determined to be in airworthy condition. Anthony Hughlett AP [REDACTED] Skyland Aircraft [REDACTED]
3.7.19				Installed new 500x5 LSA Aero classic on MLG both Left and Right ———— END. A&P [REDACTED]