DATE 2019	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	**Description of Inspections, Tests, Repairs and Alterations** Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

MAKE: Lockwood
MODEL: Aircraft
S/N: AC 248
REG. NO: N123GN
WORK ORDER:
Murrieta9394-02-2019

Gryphon Aircraft Services, LLC.

Repair Station No. CRS 2SDR271B
37680 Sky Canyon Drive
#602
Murrieta, CA 92563
Phone: 951-698-4260

DATE: 2/28/2019
A/C TSN: 0
TACH: 0

Airframe Entries

Performed initial aircraft weight and Balance.
Aircraft Empty Weight - 1198.00
Aircraft Moment - 168425.00
EWCG - 140.59
Useful load - 402

I Certify that with respect to only the work perfromed on the above identified Aircraft, Engine, Propeller or Appliance was repaired and inspected in accordance with current FAA regulations and is APPROVED for return to service.All work performed IAW applicable service manuals or other approved documentation. Pertinent details of the repair are on file at this repair facility under Work Order No. Murrieta9394-02-2019. FAA CRS #2SDR271B.

DATE: 2/28/2019 SIGNED: [redacted]

Glen Kratz
Certified Repair Station No [redacted]

Work Order: Murrieta9394-02-2019

Printed by EBis 3 (datcomedia.com)

©ASA 1993

DATE 2019	RECORDING TACH TIME	TODA FLIG

DATE 2019	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	**Description of Inspections, Tests, Repairs and Alterations** Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

ACR ELECTRONICS, Inc.
Artex Products - CAGE Code 18560
Fort Lauderdale, FL 33312

LOG BOOK ENTRY _____

E.L.T. BATTERY
REPLACEMENT DATE JAN/2025

© ASA 1993

DATE 2019 ~~18~~	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	**Description of Inspections, Tests, Repairs and Alterations** Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
5/10	7.6		0	I CERTIFY THAT THIS AIRCRAFT HAS BEEN INSPECTED IN ACCORDANCE WITH THE SCOPE AND DETAIL OF APPENDIX D TO PART 43 AND WAS FOUND TO BE IN A CONDITION FOR SAFE OPERATION" [redacted]
01 JUNE	7.6		Ø	

I find this aircraft N123GN meets the requirements for the certificate requested and have issued a Special Airworthiness Certificate dated 01 June 2019. The next inspection is due in June 2020

[redacted]

Mathew B. Hlavac [redacted]

© ASA 1993

DATE 19____	RECORDING TACH TIME	TODAY'S FLIGHT

YEAR 20 19 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	**Description of Inspections, Tests, Repairs and Alterations** Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	—	—	—	SB-912-070UL COMPLETED BY MANUFACTURER PRIOR TO DELIVERY. LOG ENTRY CONTAINED IN ENGINE LOGBOOK
3-2-19				RECEIVED WITH ENGINE. WORK COMPLETED 11/30/2017 [redacted]
1-20-18	—	—	—	MOUNTED ENGINE ON N123GN [redacted]
1-10-19	—	—	—	C/N 51-912-018 PURGING OF THE LUBRICATION SYSTEM AND HYDRAULIC VALVE TAPPET AND CHECK, CHECKED OK. [redacted]
1-14-19	—	—	—	FIRST ENGINE START. CHECKED ALL FITTINGS FOR LEAKS, NONE FOUND [redacted]

YEAR 20____ DATE	RECORDING TACH TIME	TO FLI