



Photo 1 – Quartering view of accident helicopter



Photo 2 – Aft view of helicopter at accident site



Photo 3 – Bottom of helicopter fuselage at accident site




Photo 4 – Tail rotor control assembly behind cabin