




Photo 1. Accident site, viewing west



Photo 2. Left wing section




Photo 3. Vertical stabilizer and rudder



Photo 4. Separated section of the vertical stabilizer




Photo 5. South view of the set of three power distribution lines



Photo 6. An excerpt of the Great Falls VFR sectional



Photo 7. Video camera mounted to the right wing



Photo 8. N9529Y, right-side view



Photo 9. N9529Y, rear view



Photo 10. Left-side view



Photo 11. Middle power distribution line with section of airplane sheet metal



Photo 12. The airplane engine



Photo 13. Eastern most power distribution line, north side



Photo 14. Eastern most power distribution line, south side



Photo 15. The propeller