



Photo 1 – Recovered main wreckage, right side view. (Courtesy of the FAA)



Photo 2 – Recovered main wreckage, forward right side view. (Courtesy of the FAA)



Photo 3 – Recovered main wreckage, left forward view. (Courtesy of the FAA)



Photo 4 – Recovered main wreckage, tailboom and aft side view. (Courtesy of the FAA)



Photo 5 – Recovered main wreckage, main rotor mast and cabin roof view. (Courtesy of the FAA)