



Photo 1 – Accident site, forward view. (Courtesy of Broadwater County Sheriff)



Photo 2 - Accident site, left side view. (Courtesy of Broadwater County Sheriff)



Photo 3 - Accident site, right rear view. (Courtesy of Broadwater County Sheriff)



Photo 4 - Accident site, engine and propeller assembly. (Courtesy of Broadwater County Sheriff)



Photo 5 – Accident site, forward view. (Courtesy of Broadwater County Sheriff)



Photo 6 - Accident site, view to the northwest. (Courtesy of Broadwater County Sheriff)



Photo 7 - Accident site, view to the northwest. (Courtesy of Broadwater County Sheriff)