



Photo 1 – overhead view of accident site (courtesy of Jackson County Sheriff's Department)



Photo 2 – view of left rear side of airplane at rest at accident site (courtesy of Federal Aviation Administration)



Photo 3 – view of forward section of airplane at accident site (courtesy of Federal Aviation Administration)



Photo 4 – view of engine and propeller at rest upright at accident site (courtesy of Federal Aviation Administration)



Photo 5 – view from forward right side of airplane looking aft at accident site (courtesy of Federal Aviation Administration)



Photo 6 – view of airplane upright and at rest at accident site, looking aft to forward (courtesy of Federal Aviation Administration)