



Photo 1 – Accident Site (Couresy of the airplane owner)



Photo 2 – Accident Site (Courtesy of the airplane owner)



Photo 3 - Carburetor (Courtesy of the airplane owner)



Photo 4 - Idle Mixture Adjustment Screw and Spring Assembly(Courtesy of the airplane owner)




Photo 5 – Starter Solenoid (Courtesy of the airplane owner)




Photo 6 – Starter Solenoid Damaged Wire (Courtesy of the airplane owner)