



Photo 1 – N119T Top View



Photo 2 – Top View of Cabin Area



Photo 3 – Bottom View of the Forward Fuselage



Photo 4 – Bottom View of Fuselage




Photo 5 -View of the Tail Boom and Tail Rotor Drive Shaft



Photo 6 – View of Empennage with Tail Rotor Assembly



Photo 8 – N119T Engine Assembly