



Photo 1 – Accident Airplane after Recovery (Courtesy of NTSB)



Photo 2 – View of Airplane Left Wing Center Damage from Impact (Courtesy of NTSB)



Photo 3 – Tire Marks on Runway from Accident Airplane (Courtesy of Airport Manager)