



Photo 1 – accident site photo of right rear of airplane (courtesy of Luma County Sheriff's Department)



Photo 2 – accident site photo of left rear of airplane (courtesy of Luma County Sheriff's Department)



Photo 3 – accident site photo of right side of airplane (courtesy of Luma County Sheriff's Department)



Photo 4 – accident site photo of landing path of airplane (courtesy of Luma County Sheriff's Department)