



Photo 1 – View of Accident Airplane (Courtesy of NTSB)



Photo 2 – View of Accident Airplane (Courtesy of NTSB)



Photo 3 – View of Cylinder no. 5 Piston Circlips (Courtesy of NTSB)